

Active Errata List

- Limitation to the operating conditions inside a timing and data marginal configuration
- Reading Errors
- Empty Flag Parasitic Pulse

Errata History

Lot Number	Errata List
M67206F, M672061F, M67204F all lot numbers	1, 2, 3

Errata Description

1. **Limitation to the operating conditions inside a timing and data marginal configuration.**

Rising edge of READ from 0 ns up to 8 ns (typical) before the falling edge of WRITE when only one data is left to read.

See Figure 1 for behavior description.

Failure Mode:

Empty flag glitch and following data shift out 2nd byte corruption occurs when the rising edge of the first "READ" for data shift out occurs before falling edge of the third "WRITE" for data shift in.

Worst Case Range:

between 0 ns and 11 ns

Temperature = 125°C

Voltage = 4.5V

Characterization:

-55°C / 5.5V: 6 ns

25°C / 5V: 8 ns

125°C / 4.5V: 11 ns

Workaround

These FIFOs are functional outside of the above timing and data marginal configuration.

The recommended action is to avoid this particular configuration.

Please contact Atmel for a case by case application conditions analysis.




Radiation Tolerant FIFOs

M67206F M672061F M67204F Errata Sheet



Figure 1. Behavior Description




2. Reading errors.

Description

Sometimes a bit that has been written "1" is read "0".

Failure Conditions

1. Read and write commands fall down almost at the same time, t_{WLRL} parameter in the hereunder table.
2. Write bit "0" on input port while a bit "1" is expected on output port.
3. Reading the $64^{th}+1 \pmod{64}$ ($16^{th} + 1 \pmod{16}$) for 4Kx9 FIFO) vs. the writing location.
4. Read pulse (t_{RLRH}) less than the one specified in the hereunder table.



Root Cause

The memory array of the 16Kx9 FIFO contains 64 columns, the 4Kx9 contains 16 columns. To reduce the read access time, a pipe line has been implemented on the data path. When the data_n is going out of the FIFO, the data_{n+1} is pre-fetched for the next read access. When the internal writing and reading are different from $64 \pmod{64}$ ($16 \pmod{16}$), a write and a read access are made on the same column. Coupling between the read bit-line and the write bit-line only disturbs the pre-fetch operation, forcing the sense amplifier to output "0". Then, the next external reading may be wrong.

Characterization

Worst case condition: 125°C / 4.5V

	t_{WLRL}		t_{RLRH}
	minimum	maximum	
67206H / 672061H	≥ 0 ns	≤ 8 ns	≤ 30 ns
67204H	≥ -2 ns	≤ 8 ns	≤ 25 ns

Workaround

The workaround depends of the available ways to implement it. One of these workarounds is available:

1. No read sequence while write sequence.
2. Control the gap between the read and write locations
3. Control the t_{WLRH} parameter in accordance with the above table.
4. Apply a read pulse t_{RLRH} greater than the value given in the above table.

3. Empty Flag Parasitic Pulse.

Description


A parasitic positive pulse can be observed during a FIFO write if it is applied during the read of first data of the FIFO buffer (c.f. hereunder chronograms).

Side Effect


No side effect on flags computation, internal FIFO control and data integrity.

Behavior

1. \overline{WR} wide pulse width:



2. \overline{WR} short pulse width:



In this case, the falling edge of the parasitic pulse is masked by the beginning of the regular high level of \overline{EF} flag.

Root Cause

Un-controlled delays on input signals of a flags logic decoder generate an internal glitch. This glitch is re-formatted by the on-chip ETD system (Edge Transition Detection) and a parasitic pulse is output on EF pin.

Work Around

Any of the following workarounds can be used:

1. No write sequence while read sequence.
2. \overline{EF} evaluation according to the following characterization.

Characterization

- Un-functioning window - t_{WLRH} :

	from	up to	Condition
t_{WLRH}	0 ns	10 ns	Vcc min, +125°C
	0 ns	6 ns	Vcc Max, -55°C

- Parasitic pulse delay - t_{RHEH} :

	delay	Condition
t_{RHEH}	15 ns	Vcc min, +125°C
	8 ns	Vcc Max, -55°C

- Parasitic pulse width- t_{pulse} :

	width	Comment
t_{pulse}	20 ns	Maximum



Atmel Corporation

2325 Orchard Parkway
San Jose, CA 95131, USA
Tel: 1(408) 441-0311
Fax: 1(408) 487-2600

Regional Headquarters

Europe

Atmel Sarl
Route des Arsenaux 41
Case Postale 80
CH-1705 Fribourg
Switzerland
Tel: (41) 26-426-5555
Fax: (41) 26-426-5500

Asia

Room 1219
Chinachem Golden Plaza
77 Mody Road Tsimshatsui
East Kowloon
Hong Kong
Tel: (852) 2721-9778
Fax: (852) 2722-1369

Japan

9F, Tonetsu Shinkawa Bldg.
1-24-8 Shinkawa
Chuo-ku, Tokyo 104-0033
Japan
Tel: (81) 3-3523-3551
Fax: (81) 3-3523-7581

Atmel Operations

Memory

2325 Orchard Parkway
San Jose, CA 95131, USA
Tel: 1(408) 441-0311
Fax: 1(408) 436-4314

Microcontrollers

2325 Orchard Parkway
San Jose, CA 95131, USA
Tel: 1(408) 441-0311
Fax: 1(408) 436-4314

La Chantrerie
BP 70602
44306 Nantes Cedex 3, France
Tel: (33) 2-40-18-18-18
Fax: (33) 2-40-18-19-60

ASIC/ASSP/Smart Cards

Zone Industrielle
13106 Rousset Cedex, France
Tel: (33) 4-42-53-60-00
Fax: (33) 4-42-53-60-01

1150 East Cheyenne Mtn. Blvd.
Colorado Springs, CO 80906, USA
Tel: 1(719) 576-3300
Fax: 1(719) 540-1759

Scottish Enterprise Technology Park
Maxwell Building
East Kilbride G75 0QR, Scotland
Tel: (44) 1355-803-000
Fax: (44) 1355-242-743

RF/Automotive

Theresienstrasse 2
Postfach 3535
74025 Heilbronn, Germany
Tel: (49) 71-31-67-0
Fax: (49) 71-31-67-2340

1150 East Cheyenne Mtn. Blvd.
Colorado Springs, CO 80906, USA
Tel: 1(719) 576-3300
Fax: 1(719) 540-1759

Biometrics/Imaging/Hi-Rel MPU/ High Speed Converters/RF Datacom

Avenue de Rochepleine
BP 123
38521 Saint-Egreve Cedex, France
Tel: (33) 4-76-58-30-00
Fax: (33) 4-76-58-34-80

Literature Requests

www.atmel.com/literature

Disclaimer: Atmel Corporation makes no warranty for the use of its products, other than those expressly contained in the Company's standard warranty which is detailed in Atmel's Terms and Conditions located on the Company's web site. The Company assumes no responsibility for any errors which may appear in this document, reserves the right to change devices or specifications detailed herein at any time without notice, and does not make any commitment to update the information contained herein. No licenses to patents or other intellectual property of Atmel are granted by the Company in connection with the sale of Atmel products, expressly or by implication. Atmel's products are not authorized for use as critical components in life support devices or systems.

© Atmel Corporation 2006. All rights reserved. Atmel® and combinations thereof are the registered trademarks of Atmel Corporation or its subsidiaries. Other terms and product names may be the trademarks of others.



Printed on recycled paper.