

Fiber Optic Products

Fiber Optic Cable Assemblies

AMP **2-504949-5** **Active** [Active](#)[Not Reviewed for ELV/RoHS Compliance](#)**(Tyco Electronics P/N: 2-504949-5)**[Search for Parts](#)

Document links for this part cannot be displayed. Your browser does not support inline frames or is currently configured not to display inline frames. Inline frames are supported in both Internet Explorer 5 and Netscape 6, as well as all later versions of these browsers.

Related Part Information		
General Information	eCommerce	Related Part Information
General Info	Pricing	Tooling
Sales Info	Product Availability	
Assembly Subcontractors		

Searchable Features:

Brand:	AMP
Product Type:	Cable Assembly
Cable Assembly Type:	MPO to MPO
Fiber Type:	62.5/125
Mode:	Multimode
Cable Type:	Mainframe
Cable Diameter (mm [in]):	4.90 [.193]
No. of Fibers:	8
Fiber Path Configuration:	Flipped
No. of Channels:	4
Flammability Rating:	Plenum (UL OFNP/CSA FT-6)
Cable Buffering:	Tight Buffered Easy Strip

Other Properties:

Comment: Pulling sock included on each end of the cable assembly.

Cable Color:	Orange
Length (M [ft]):	30.50 [100.064]
Mode Conditioned Launch Cable Assembly:	No
Connector(s) Exit Angle to Connector(s) Exit Angle:	180° to 180°
Boot Body Style - Left:	Standard
Boot Color - Left:	Black
Boot Body Style - Right:	Standard
Boot Color - Right:	Black
Ferrule Material:	Polymer Composite
Fibre Channel:	No

[Copyright](#) and [Privacy Statement](#)

Visit [Tyco International, Ltd.](#)

[Products](#) | [Catalog](#) | [Brands](#) | [Industries](#) | [Commerce](#) | [Supplier](#) | [Contact Us](#) | [About](#) | [Home](#)

i2 Technologies US, Inc.

HTML Pages converted to PDF Document

This document contain component information from the manufacturer's website which are not available in a revision controlled document from the manufacturer. To facilitate the addition of these parts into the Electronics Database, we are converting the HTML pages related to that part, from the manufacturer's website into Adobe PDF format. The contents of this document is based on the information provided on the manufacturer's website, therefore the information may have been changed by the manufacturer since this was created.

