




RECOMMEND SOLDERING CONDITIONS

for:CL/ CLH/ SQV/ SMD power inductors/ SMD Chip Beads/ SMD Filters, Transformers, Current Sensors



| | |
|-----------------------|-------|
| for: lead solder | ————— |
| for: lead-free solder | |