



REVISION H


RECOMMENDED BOARD LAYOUT



NOTE: OUTER ROWS MAY NOT NEED VIAS - THIS IS LEFT TO THE DISCRETION OF THE BOARD DESIGNER.



RECOMMENDED STENCIL LAYOUT STENCIL TO BE .0060[0.152] THICK



PROPRIETARY NOTE

THIS DOCUMENT CONTAINS INFORMATION CONFIDENTIAL AND PROPRIETARY TO SAMIEC, INC. AND SHALL NOT BE REPRODUCED OR TRANSFERRED TO OTHER DOCUMENTS OR DISCLOSED TO OTHERS OR USED FOR ANY PURPOSE OTHER THAN THAT WHICH IT WAS OBTAINED WITHOUT THE EXPRESSED WRITTEN CONSENT OF SAMIEC, INC.

samtec

520 PARK EAST BLVD, NEW ALBANY, IN 47150 PHONE: 812-944-6733 FAX: 812-948-5047 e-Mail info@SAMTEC.com code 55322

SHEET SCALE: 4:1

DESCRIPTION:

VITA 42 (LEAD FREE) SOCKET ASSEMBLY

DWG. NO.

ASP-103612-02

F:\DWG\MISC\MKTG\ASP-103612-02-MKT.SLDDRW

BY: WHELAN 09/12/06

SHEET 2 OF 2